



Precision Press Products, LLC
800-510-4181 or 816-887-5831
Fax 816-887-5834

Page Pack Ink Module, Injector Screw and Bronze Bushing

At the request of many of our customers, we are now cleaning and testing these page pack ink modules. We totally disassemble these modules, ultrasonic clean them and re-assemble them. After re-assembling we test and clean the potentiometers to make sure they are good. We also have found that the wiring coming from the 5 pin connector to the potentiometer is much too dirty and contaminated with ink and other chemicals to be re-used, so we totally replace this wiring. Many of our customers have indicated that they have numerous problems with the silver colored 5 pin connectors. They have stated that they would prefer that we replace them with the gold 5 pin connectors, so we will be doing this at the time we re-wire the assembly. We currently only have the later assembly (E18106-1) in stock. We will do everything possible to keep a sufficient number of each of these part numbers rebuilt and ready to ship at all times.



Quantity	Part Number	Description	Price Per Part
1	PPP-E18106-1	Page Pack Ink Modules <ul style="list-style-type: none">• Rebuilt and Cleaned• Outright Purchase• While Supplies Last	\$60.00 Each